




Load Meter

Blue Arrow CLY-AS Dynamometer



unit:mm

kN lb kg CE AA PEAK
Lb/kg/kN Applicable in Built-in
selectable day and night beeper
battery

Technical Specifications

Accuracy: 0.1%F.S.
Time to Stable Reading: ≤8s
Maximum Safe Load: 150%F.S.
Ultimate Overload: 500%F.S.
Overload Alarm: 100%F.S.+9e
Operating Temperature: -10°C ~ 40°C
Storage Temperature: -20°C ~ 60°C

Features

- Strong and light dynamometer to weigh the force of gravity or the pulling force
- Superior alloy steel, preferable to dynamometers with larger capacity
- In weighing the pulling force, the dynamometer has the functions of peak
- In weighing the force of gravity, the dynamometer support kg/lb conversion
- 6 digit 18mm FSTN LCD display with LED backlighting

Max Capacity	Division	Weight	L	L1	H	H1	B	B1	E
3000kg	1kg	3kg	220	170	115	50	55	38	26
5000kg	2kg	4kg	235	177	115	56	55	38	31
10000kg	5kg	6kg	283	203	115	83	55	38	41
20000kg	10kg	14kg	349	237	115	115	73	56	57
30000kg	10kg	19kg	410	270	120	120	84	67	71

Distributor (US and Canada)
Optoco Inc.
600 - 2498 West 41st Ave
Vancouver, BC, V6M 2A7
Tel: 778-706-6933
Email: info@optoco.ca
Web: www.crane-scale.com

Specifications are subject to change without notice.